Gubi 1 Chair Hirek

Assembly instruction



Products:

Gubi Chair shell - hirek, steel sledge base – non stackable, 4 pcs 50x16 round washer head screw, 4 pcs M6 washer, 4 pcs Wing repair washer, 4 pcs plastic feet

Tools:

Akku drill or screwdriver with Torx 25 bit

Products:

4x ISO 7380 M4x6, 4x glides (Ackurat):

- 347A -NATUR (Chrome frame)
- 347F SVART (Black frame)
- 347H FILT SVART (Black frame + felt)
- 3470 FILT NATUR (Chrome frame + felt)



4 pcs 50x16 torx DELTA PT round washer head screw Bossard Art. No. 3187118,

4 pcs washer 15x6,4x1,5 mm Würth Art. No. 0411615.
4pcs M6 Wing repair washer

(6,4X40X1,5 - DIN 522 // Würth: 04116

(6,4x40x1,5 - DIN 522// Wurth: 0411)


Products:

Gubi chair shell – hirek, 4 pcs M6 Wing repair washer

Action:

Turn the shell upside down, so the holes on the backside of the seat is visible and faces upwards. Place 4 pcs washer on the bottom of the shell and align them with the holes.









Gubi 1 Chair Hirek

Assembly instruction



Products:

Gubi Chair shell – hirek, steel sledge base - non stackable

Action:

Place the steel base on top of the shell, so the 4 holes on the base are above the holes in the shell.



Gubi chair shell – hirek, steel sledge base – non stackable, 4 pcs 50x16 round washer head screw, washer 15x6,4x1,5 mm

Action:

Put all 4 pcs screw with washers on through the frame into the shell

Products:

Gubi chair shell – hirek, steel sledge base – non stackable, 4 pcs 50x16 round washer head screw, washer 15x6,4x1,5 mm

Action:

Make sure that all screws are correct into the thread in the shell

Action:

The screws can be tightened with a screwdriver or an Akku drill.

Extremely Important! Do not tighten screws with more than 2 Nm.

The screws must not be tighten to much – then they will damage the holes in the shell and the shell cannot be repaired.









Gubi 1 Chair Hirek

Assembly instruction



Action:

Make sure all screws has been tighten properly



Gubi chair frame, Würth DOS thread locking agent MEDIUM, Art. No. 0893243050

Action:

Apply a suitable amount of the locking agent in the 4 pcs mounting holes in the frame



Gubi chair frame, Würth DOS thread locking agent MEDIUM, Art. No. 0893243050, 4x glides (glide-color changes with frame color)

Action:

Mount the screw through the glide and into the threaded hole in the frame.

Action

Turn the chair around and place it on the legs.

The Gubi chair is ready for use.







